


FIG.1



16869P-035200US

FIG. 2




FIG.3





FIG.4



20052382 • 07/12/2022

FIG.5




FIG.6





FIG.7



10052262-C11306

FIG.8




FIG.9




FIG.10




FIG.11

#	DATE AND TIME DATA SENT	USER ID	GROUP ID	REQUESTED SERVICE ID
1	2001062712235606	usr_676001027	grp_105	e-key_room_a
2	2001082015231302	usr_676001028	grp_301	print_room_b
...

FIG.12

#	DATE AND TIME DATA RECEIVED	USER'S PERIPHERAL DEVICE INFORMATION
1	2001062712235606	[info_udev]
2	2001082015231302	[info_udev]
...

FIG.13

ACCESS LEVEL	GROUP ID	USER'S PERIPHERAL DEVICE INFORMATION	EQUIPMENT PERIPHERAL DEVICE INFORMATION
1	grp_105	[info_udev]	[info_ddev]
2	grp_301	[info_udev]	[info_ddev]
...

FIG.14

ACCESS LEVEL	EXECUTION PROCESSING	ACCESS RIGHTS
0	PROCESSING 1	×
	PROCESSING 2	×
	PROCESSING 3	×

1	PROCESSING 1	×
	PROCESSING 2	○
	PROCESSING 3	×

...

10053222 04.3.2022

FIG.15




FIG. 16




FIG.17



#	SERVICE	PERIPHERAL DISTANCE [m]
1	DOOR UNLOCKING	10
2	DOOR LOCKING	0
...

FIG.18




FIG.19




FIG.20




FIG.21




FIG.22




FIG.23

INFORMATION RECEIVED	TIME (BAND)	ACCESS LEVEL
inf_receive	AM	1
inf_receive	PM	2
...

FIG.24




FIG.25

#	TIME	STATUS (VALUE)	PERIPHERAL EQUIPMENT
1	2001.1.1.16:25:06	ON	PC_2L, ELV_2L, ...
2	2001.1.2.12:55:26	OFF	PC_1L, ELV_1L, ...
...

FIG.26

ACCESS LEVEL	TARGET EQUIPMENT	REFERENCE STARTING POINT	REFERENCE END POINT	HISTORY INFORMATION
0	EQUIPMENT 1	P: BOOKS S: LOAN ALLOWED	P: FRONT GATE S: LOAN NOT PERMITTED	P [REQUESTED EQUIPMENT] S [REQUESTED EQUIPMENT], ... T: 2001.1.16:25:06 T: 2001.1.16:25:06 P [REQUESTED EQUIPMENT] T [REQUESTED EQUIPMENT],
1	EQUIPMENT 2

FIG.27

